



#WORKINGSMARTER

SAFETY & USER INSTRUCTIONS

Drill wall in normal manner taking care to avoid cables, pipes etc. whether hidden or not.“

Brick-burst” can be minimised by switching to rotary only mode or applying less pressure for last portion of drilling.

When drilled through the wall, re-drill moving the bit backwards and forwards through the hole to clear any debris and make a smooth internal hole.

Be careful when handling the drill bit after drilling as it may be hot at the tip end.

Disconnect power from the drilling machine. Remove drill bit from drilling machine BUT leave the drill in the wall exposed at each side of the wall.

Do not thread cable that is already connected to power supplies.

Cable to be threaded can be tied onto drill bit using either the hole in the shank or the tip.

Cable can be pushed or pulled through hole produced using the Cable Guide drill bit.

Maximum cable diameter is 16 mm.

